
Signicade® MDX

[PLASTICADE®]



Sand Ballasting Instructions



Sand Fill Hole


Each sign frame has two fill holes, one on each half of the frame.

Remove plug from fill hole and fill each hole with dry sand. Shake the sign frame to evenly distribute the sand at the bottom of the frame.


2 lbs. of sand per hole for a total of 4 lbs. per sign frame is recommended.

Play sand is suggested for ease of filling.


Sign Insertion Instructions:




 Slide sign down through the tabs



Slide through, pulling sign in front of bottom slot until sign hits the ground



3. Push sign up into top slot



4. Slide sign down into bottom slot